






A (x2)



B (x2)



C (x1)



D (x1)



E (x1)



F (x1)



G (x1)



H (x2)



I (x2)



J (x1)



K (x4)



L (x1)
M5x16



M (x1)
M10x20



N (x4)
M6x10



O (x4)
M4x8



P (x1)
4mm



Q (x1)
6mm



M-A (x4)
M4x12




M-B (x4)
M5x12





M-C (x4)
D5


1





2



















3





4

